

VEHICLE INSPECTION REPORT

PO70YBF

FIAT DUCATO 35 2.3 MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	03/11/2020	VIN	ZFA25000002P43850	CAP Below	£3,925.00
Year	2020	Body Style	Dropside LWB	Gearbox	MANUAL
Mileage	90,309 Miles Warranted	MOT Due	09/11/2025	Gears	6
Fuel Type	Diesel	CAP Clean	£5,375.00	Tail Lift	Column
Colour	WHITE	CAP Average	£4,800.00		

CLUTCH / GEARBOX ISSUES, NO GEARS TOW BAR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door Moulding nsf
Missing
Replace



7: Lamp osr
Broken
Replace



8: B Post os
Scratched
Over 25mm Thru Paint



9: Door osf
Dented
Over 30mm



10: Door Mirror Glass os
Broken
Replace



11: Wing osf
Dented
With Paint Damage



12: Screen Front
Chipped
Over 10mm



13: Fascia Panel
Missing
Replace



14: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		