

VEHICLE INSPECTION REPORT

OE21JUJ

Mercedes-Benz SPRINTER 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Avonmouth

Reg. date 19/08/2021

Year 2021

Mileage 105,598 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN W1V9071352N159385

Body Style Dropside L3

MOT Due 21/08/2027

CAP Clean £18,700.00

CAP Average £16,700.00

CAP Below £13,700.00

Gearbox MANUAL

Gears 6

Tail Lift Column

TOW BAR

Tyres

NSF

NSR

OSF



OSR






Spare

Features


- Park assist camera
- Front electric windows

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Wing nsf
Scratched
UpTo 25mm Thru Paint



3: Door nsf
Chipped
Multiple Chips

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Flasher Side Repeater ns
Broken
Replace

6: B Post ns
Chipped
Multiple Chips



7: B Post os
Chipped
Multiple Chips

8: Door osf
Chipped
Multiple Chips



9: Door osf
 Scratched
 Over 25mm Thru Paint

10: Bumper Front
 Scratched
 Over 100mm Thru Paint



11: A Post os
 Chipped
 Multiple Chips

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			